



C-AD ACTIVITY JANUARY 2017



FEBRUARY 2017



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM -- FEBRUARY 2017

p^ source

Vacuum Cryo Pump Compressors failed

Controls Software

Injection Drift corrections found to be zero

RF_AGS

Ilrf mis-configuration -- magnet quenches at injection

QLI

Four beam induced quenches

PS_RHIC

bo7-tq4-ps

bi5-tv4-ps replaced

bo3-snk7-1-4.ps replaced

RF_RHIC


Acceleration Cavities tripping off

YA1 driver replaced

PPS_RHIC

Abort Kicker pre-fires

1Y, 5B



Run17 availability

